S-18645

25X1C

CENTRAL INTELLIGENCE AGENCY
PHOTOGRAPHIC INTELLIGENCE DIVISION
PHOTOGRAPHIC INTELLIGENCE REPORT

ASSESSMENT OF STATUS OF BOMBED BRIDGES NORTH VIETNAM

CIA/PIR-5007/65

JUNE 1965



Declass Review by NIMA/DOD

WARNING

This document contains information affecting the national defense of the United States, within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

ME FOREIGN DISSEN

GROUP 1 Excluded from outsmotic dewagesding and declassificati

25X1C

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

ASSESSMENT OF STATUS OF BOMBED BRIDGES, NORTH VIETNAM

- 1. This photo intelligence report is a study of the status of bombed bridges in North Vietnam and an assessment of repair work on these bridges or other compensative action taken by the North Vietnamese. A locator map (CIA/PID/IB-P-566/65) and an annotated photo of each bridge (CIA/PID/IB-P-567/65 thru P-587/65) are enclosed with this report.
 - 2. An analysis of each bridge is as follows:
 - A. Phuc Thiem Highway Bridge (CIA/PID/IB-P-567/65)

1. Status: Destroyed

- 2. Compensative Action: None apparent
- B. Khe Kien Highway Bridge (CIA/PID/IB-P-568/65)

1. Status: Destroyed

- 2. Compensative Action: Causeway with culvert
- C. Kim Cuong Highway Bridge West (CIA/PID/IB-P-569/65)

1. Status: One span destroyed

- 2. Compensative Action: Newly constructed ford
- D. Dong Hoi Highway Bridge (CIA/PID/IB-P-570/65)
 - 1. Status: Two spans destroyed, three spans severly damaged, one span moderately damaged.
 - 2. Compensative Action: Newly constructed ferry crossing
- E. Xom Phuong Highway Bridge (CIA/PID/IB-P-571/65)
 - 1. Status: Two bridges; west bridge two spans destroyed,
 three spans dislocated; east bridge-four spans
 destroyed.
 - 2. Compensative Action: None
- F. My Duc Highway Bridge (CIA/PID/IB-P-572/65)
 - 1. Status: One span destroyed, one span dropped, approach damaged.
 - 2. Compensative Action: None apparent
- G. Thanh Yen Highway Bridge (CIA/PID/IB-P-573/65)
 - Status: Damaged decking and truss members, one pier and two spans destroyed.
 - 2. Compensative Action: Reactivated ferry crossing
- H. Xom Gia Highway Bridge (CIA/PID/IB-P-574/65)
 - 1. Status: One span dropped
 - 2. Compensative Action: Newly constructed ferry crossing

SECRET

25X1C

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

- I. The Son Highway Brigge (CIA/PID/IB-P-575/65)
 - 1. Status: One span destroyed, two spans superficially damaged
 - 2. Compensative Action: Newly constructed ferry crossing
- J. Tam Da Railroad & Highway Bridge (CIA/PID/IB-P-576/65)
 - 1. Status: Two spans destroyed, one span damaged, approaches damaged
 - 2. Compensative Action: Reactivated ferry crossing
- K. Ly Nhan Highway Bridge (CIA/PID/IB-P-577/65)
 - 1. Status: Approach cratered, two spans destroyed, one span severely damaged, one span moderately damaged, one span superficially damaged, and one pier severely damaged.
 - 2. Compensative Action: Reactivated ferry crossing
- L. Phuong Can Highway Bridge (CIA/PID/IB-P-578/65)
 - 1. Status: One span had been dropped. Dropped span has been replaced by temporary deck span for light traffic.

 Truss is under construction.
 - 2. Compensative Action: Reconstruction of Bridge underway, newly built ferry crossing near by.
- M. Qui Vinh Railroad Bridge (CIA/PID/IB-P-579/65)
 - 1. Status: Bridge severely damaged, one span dropped, approaches cratered.
 - 2. Compensative Action: The traffic that had previously used this bridge is now using a small newly constructed ferry crossing near by.

 Bomb craters in approaches have been filled in.
- N. Thanh Hoa Bridge (CIA/PID/IB-P-580/65)
 - 1. Status: Bombing had crimped one section of the bridge,
 destroyed three sections of the roadway, cut one member,
 and interdicted the east approach.
 - 2. Compensative Action: Pier supports have been installed under crimped section, the cut member has been patched, and the east approach has been improved. The rail portion of the bridge is being utilized as a road. This bridge is apparely able to support heavy truck traffic. There is a reactivated ferry crossing just south of the bridge.
- O. Dong Phong Thuong Railroad & Highway Bridge (CIA/PID/IB-P-581/65)

 1. TStatus: Bombing had collapsed center section of the bridge

 and interdicted the north approach.

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

- Compensative Action: A temporary deck span in place of the collapsed section. The dropped truss apparely being used to support the temporary deck. The interdicted approach has been filled. This bridge is apparently capable of supporting heavy traffic. A newly constructed ferry crossing is located just east of the bridge.
- P. Trai Hoi Railroad Bridge (CIA/PID/IB-P-582/65)
 - 1. Status: One span destroyed, one span damaged, NW approach destroyed.
 - 2. Compensative Action: No work has been done on bridge. There is a ferry crossing adjacent to the west, probably used for local traffic.
- Q. San Dinh Highway Bridge (CIA/PID/IB-P-583/65)
 - 1. Status: Bridge destroyed
 - 2. Compensative Action: None
- R. Dien Chau Railroad Bridge (CIA/PID/IB-P-584/65)
 - 1. Status: Two spans destroyed, south approach interdicted.
 - 2. Compensative Action: None
- S. Xom Ca Trang Highway Bridge North (CIA/PID/IB-P-585/65)
 - 1. Status: Destroyed
 - 2. Compensative Action: Newly constructed ford
- T. Xom Ca Trang Highway Bridge (CIA/PID/IB-P-585/65)
 - 1. Status: One span destroyed
 - 2. Compensative Action: Previous ford reactivated
- U. Bai Duc Thon Railroad & Highway Bridge (CIA/PID/IB-P-586/65)
 - 1. Status: Approaches destroyed, minor truss damage.
 - 2. Compensative Action: None
- V. Bai Duc Thon Highway Bridge (CIA/PID/IB-P-587/65)
 - 1. Status: One span destroyed, severe damage to entire bridge.
 - 2. Compensative Action: New ford west of the bridge. Mission

shows span under repair nearing completion.

25X1D

Approved For Release 2000/09/06 : CIA-KDF76100459A000000220076-1

25X1C

SECRET NO FOREIGN DISSEN CIA/PIR-5007/65

CIA, PHOTOGRAPHIC INTELLIGENCE DIVISION

REFERENCES

PHOTOGRAPHY

25X1D


MAPS OR CHARTS


Annotated locator map (Indochia terrain and transportation 50973 1-65)

REQUIREMENT


ORR C-RR5-82,566

CIA/PID PROJECT 30656-5





















25X1C SECRET ROUTE I FERRY CROSSING THO SON HIGHWAY BRIDGE 182722N/1054643E 25X1D SECRET D FOREIGN DISSEN 25X1C

